

**Mastercam X<sup>7</sup>**

**TRAINING**

**GUIDE**



**FOUR-AXIS-LESSON-3**

**camInstructor**

### Objectives

In **Four-Axis-Lesson-3** you will generate the toolpaths to machine the part on a CNC vertical milling machine with four-axis capability. The outside diameters have already been completed.

The part will be held in a rotary indexer as shown below. These types of indexes can utilise collets or a three-jaw chuck. This Lesson covers the following topics:

➤ **Open an existing file containing:**

The solid geometry for the part

➤ **Establish Stock Setup settings:**

Use a supplied StereoLithography (STL) file for toolpath verification  
Material for the part  
Feed calculation



➤ **Generate milling toolpath consisting of:**

Using the View Manager  
Using Views, Levels, Tool Planes and Construction Planes  
Create Contour, Pocket and Drill toolpaths  
Using Toolpath Transform to rotate toolpaths

➤ **Inspect the toolpath using Mastercam's Verify and Backplot by:**

Launching the Verify function to machine the part on the screen  
Generating the NC- code






## TOOL LIST

- ☉ Two cutters will be used to create this part.
- ☉ 0.75 diameter flat end mill
- ☉ 0.25 diameter flat end mill

# FOUR-AXIS-LESSON-3 - THE PROCESS

- TASK 1:** Setting the environment
- TASK 2:** Introduction - Watch the video
- TASK 3:** Open an existing file
- TASK 4:** Identify the entities on each level
- TASK 5:** Machine the first face of the hexagon
- TASK 6:** Machine remaining faces of hexagon using Transform Toolpath
- TASK 7:** Machine the first face of the square
- TASK 8:** Machine remaining faces of square using Transform Toolpath
- TASK 9:** Machine Pocket on BACK face
- TASK 10:** Machine Open Pocket on BOTTOM face
- TASK 11:** Machine Pocket on TOP face
- TASK 12:** Drill holes on FRONT face
- TASK 13:** Drill hole on Hexagon at front
- TASK 14:** Drill hole on Hexagon at back using Transform Toolpath
- TASK 15:** Verify toolpaths using a supplied STL file
- TASK 16:** Post and create the CNC code file



### ☉ Getting Started

Before working through these lessons you may find it useful to review the material in the **Tips and Techniques** section of the multimedia DVD that came with this text covering **Work Coordinate Systems (WCS)**.

If you are using the Online Course content the Work Coordinate Systems (WCS ) material is in the Tips and Techniques section of the main menu.


### TASK 1: SETTING THE ENVIRONMENT

Before starting the geometry creation you should set up the grid, toolbars and machine type as outlined in the **Setting the environment** section at the beginning of this text:

1. Set up the **Grid: Size= 1.0, X & Y Spacing= 0.25**. This will help identify the location of the origin.
2. Customize the toolbars to machine a **4-5 Axis part**.

### TASK 2: INTRODUCTION – WATCH THE VIDEO


1. Before you start to work on this Lesson review the Introduction video on the multimedia DVD that came with this text. You will find the video in the **“Four-Axis-Lesson-3”** section, it is entitled **Introduction - 2 Minutes**. If you are using the Online Course content the video is available in this Lesson on the online content screen.
- The video will review the techniques that will be used to generate the toolpaths utilizing the indexing table.



### TASK 3: OPEN AN EXISTING FILE

➤ If you are using a Training Guide to go through this Lesson the required file is on the multimedia DVD that came with this text in a folder called **Mastercam Files**. If you are using the Online Course content the file is available in this Lesson on the online content screen. The part is already setup for a: **GENERIC HAAS 4 AXIS MILL**.

1. Select **File>Open> Four-Axis-Lesson-3**. File is shown below in shaded view.
2. Select **File>Save as...**
3. In the File name box, type **Four-Axis-Lesson-3**.
4. Save to an appropriate location.
5. Select the green check mark button  to save the file and complete this function.




## TASK 4: IDENTIFY THE ENTITIES ON EACH LEVEL

☞ Before you start to work on the toolpaths lets first identify the entities on each Level.


- ☞ Levels are a primary organizational tool in Mastercam. A Mastercam file can contain separate levels for wireframe, surfaces, drafting entities, and toolpaths.
- ☞ By organizing your files into levels, you can more easily control which areas of the drawing are visible at any time and which parts are selectable so that you do not inadvertently make changes to areas of the drawing you do not want to change.



1. Activate a shaded view by selecting the icon at the top of the screen.
2. From the **Status** bar at the bottom of the screen select **Level**.
  - ☞ **The Level Manager dialog window will now appear.**
  - ☞ **As you can see in the picture below there are four Levels in this part.**
  - ☞ **Level 1 contains the Part geometry**
  - ☞ **Level 2 contains the Text, TOP, BOTTOM, BACK and FRONT.** This is on the part to help you with the orientation of the part as you work through creating the toolpaths
  - ☞ **Level 3 contains the Curves that were previously created for the STL file geometry**
  - ☞ **Level 4 contains the Solid geometry that was previously created for the STL file geometry**
  - ☞ **Level 1 and 2 are visible as noted by the X in the Visible column.**
3. Turn off **Make main level always visible** as shown below.




- Now make visible **only Level 4 SOLID-STL**. Click in the **Visible column** for the various Levels so that the only X that appears is in the Visible column for Level 4.




- Select the OK button  to exit the **Level Manager** dialog box. On the screen is the Solid Extrude used for the STL file. This STL file will be used to verify the toolpaths.




- From the **Status** bar at the bottom of the screen select **Level**.
- Now make visible **only Level 3 CURVES-STL**. Click in the **Visible column** for the various Levels so that the only X that appears is in the Visible column for Level 3.




8. Select the OK button  to exit the **Level Manager** dialog box. There are only two circles on this level. These two circles were used to create the Solid Extrude used to for the STL file.



9. From the **Status** bar at the bottom of the screen select **Level**.
10. Now make visible **only Level 1 and 2**. Click in the **Visible** column for the various Levels so that the only X that appears is in the Visible column for Level 1 and 2. Set remaining options and values as shown below.




11. Select the OK button  to exit the **Level Manager** dialog box.




**TASK 5:**  
**MACHINE THE FIRST FACE OF THE HEXAGON**

☞ In this task you will use the 0.75" diameter flat end mill to rough and finish the first face of the hexagon using Toolpath> Contour. In the next task you will use Toolpath>Transform to machine the remaining faces of the hexagon.




1. Set the graphics view to **Isometric View**.

2. Select the **Screen Fit** icon found at the top of the screen to fit the part to the screen .



**Note**  
 At the bottom of the graphics screen the status of the **Tool and Construction** plane is set to **TOP**.

3. Now dynamically rotate the display similar to the display shown below. The text **TOP** is facing up.




**Tool plane (Tplane)**  
 For most typical toolpaths, this is the plane in which cutting moves (G1/G2/G3) take place.  
 The tool typically approaches and retracts from the part normal to the tool plane in the Z axis.  
 You can align the Tplane with any of the standard planes or a custom orientation.

4. Activate a wireframe view by selecting the icon at the top of the screen.





5. From the menu bar select **Toolpaths>Contour...**
6. When prompted to **Enter new NC name** ensure **FOUR-AXIS-LESSON-3** is displayed and then select the OK button .
7. On the screen you will now see the **Chaining dialog box**. Select **Single chain**.




**Single**  
Creates a chain out of a single line, arc, or spline.


8. On the graphics screen is now a prompt to **Select contour chain 1**. Zoom in as required and select the single line shown below:




9. After selecting the line your graphics screen should look like the screenshot below, with the **green arrow pointing left**. If the arrow is not pointing to the left select the arrow  from the Chaining dialog box to reverse the direction.




10. After the contour has been successfully chained select the OK button  at the bottom of the Chaining dialog box.
11. Ensure the **Toolpath Type** is set to **Contour**.



12. On the left of the dialog box select **Tool**. Click on the **Select library tool** button and choose a **3/4" Flat End Mill**. Make changes to this page as shown below:




13. Select **Cut Parameters** from the list on the left and make changes to this page if required.



14. **Depth Cuts** should not be activated.



15. Select **Lead In/Out** from the list on the left and make changes to this page as shown below:




16. **Break Through** should not be activated.




## Mastercam Training Guide


17. Select **Multi Passes** from the list on the left and ensure **Multi Passes** are activated by clicking on the small Multi Passes box. Make changes to this page as shown below:



18. Select **Linking Parameters**. Input the depth of 0 and the other values as shown below:



19. Scroll down the list on the left and select **Planes(WCS)**. Set the Work offset to **Zero**.




**Work Offset #**  
Assigns a work offset code to the view. When you use the view for a Tplane and create a toolpath.

Mastercam will automatically output the work offset when you post the operation. Number the offsets sequentially from zero, or enter -1 to not assign any offset to the view.

**Work Offset #** Setting this value to **Zero** will out a **G54** in the CNC code file.

```
N1 G20
N2 G0 G17 G40 G49 G80 G90
N3 T1 M6
N4 G0 G90 G54 X.1875 Y-.005 A0. S4500 M3
N5 G43 H1 Z2.
N6 M8
```

20. When confronted with the **Update View** dialog box activate **Update just this operation without changing the view**.



21. Click on the OK button when done .

22. Select Coolant from the list on the left. Open up the drop down menu for Flood and set it to On.


23. Select the OK button  to exit Contour parameters.

24. Save your Mastercam file.


25. Backplot this toolpath.

## TASK 6: MACHINE REMAINING FACES OF HEXAGON USING TRANSFORMTOOLPATH


- ☞ In this task you will use Transform Toolpath to rotate the first contour toolpath to complete the machining of the remaining faces of the hexagon.



1. In the Toolpaths manager **select only the first contour** operation, as indicated by the blue checkmarks shown below.





2. From the menu bar select **Toolpaths>Transform...**  
3. On the **Types and Methods** page set the following. **Ensure** there is a check for the contour operation in the **Source operations** list. Set options as shown below:






4. Now click on the **Rotate** tab and set the following:



**Start angle**  
  
 Sets the beginning angle for the rotate toolpath.


**Rotation angle**  
  
 Sets the angle of rotation for the transform toolpath.

5. Next activate **Rotation view** and then click on the **Select view** icon.



**Rotation view**  
 Select this option to rotate the transformed toolpaths in a different plane than the original. If this option is inactive, the toolpath rotates in the original tool plane.

6. You will be confronted with the **View Selection** dialog box, select **RIGHT SIDE** and deactivate **Set new origin** as shown below:



## Mastercam Training Guide


---

7. Select the OK button  to exit the **View Selection** dialog box.
8. Select the OK button  to exit the **Transform Operations Parameters** dialog box.
9. **Save** your Mastercam file.


10. Activate a shaded view by selecting the icon at the top of the screen.



11. Backplot all the toolpaths.

12. To pick all the operations to Backplot pick the **Select All** icon  circled below:


26. The next step is to select the **Backplot selected operations** icon shown below:



27. **Maximize** the Backplot/Verify window if required.

28. Select the **Home** Tab if required.


29. Activate the options shown below in the **Visibility** section of the Home tab.



30. Click on the **Backplot** tab at the top left of the screen.



31. Activate the **Both** option in the Toolpath section of the Backplot tab.




32. In the lower right corner of the screen now set the run **Speed** to slow by moving the slider bar pointer over to the left as shown below.




33. Now select the **Play Simulation** button to review the toolpaths.



34. After reviewing the Backplot of the toolpath use the **Close** button  to exit Backplot.

☞ Your part should look similar to the screen shot below.




Sample  
not for  
Distribution


## TASK 7:

### MACHINE THE FIRST FACE OF THE SQUARE


- In this task you will use a 0.75" diameter flat end mill to rough and finish the first face of the square.
- For this example you will copy the first contour operation used to machine the first face of the hexagon and then modify the copied operation to machine the first face of the square.







1. Activate a wireframe view by selecting the icon at the top of the screen.
2. In the Toolpaths manager **select only the first contour** operation, as indicated by the blue checkmarks shown below. The contour operation for the hexagon is the first operation.




3. To copy this operation **Hold down the Right mouse button over the folder for this operation. Keep holding the right mouse button** down and drag below the red arrow and release.
4. Select **Copy after** from this menu.




5. Your screen will look similar to the screenshot below on the left. Move the Insert arrow  to the bottom of the list of operations by clicking the  icon on the Toolpaths Manager toolbar:




6. In the **Toolpaths Manager** click on the Geometry icon for the **third** operation as shown below:




7. In the Chain Manager right mouse click on **Chain 1** and select **Rechain Single**.






8. On the screen you will now see the **Chaining dialog box**. Select **Single chain**.




9. On the graphics screen is now a prompt to **Add chain 1**. Zoom in as required and select the single line shown below:




10. After selecting the line your graphics screen should look like the screenshot above, with the **green arrow pointing left**. If the arrow is not pointing to the left select the arrow  from the Chaining dialog box to reverse the direction.
11. After the contour has been successfully chained select the OK button  at the bottom of the Chaining dialog box.
12. Select the OK button  at the bottom of the Chain Manager box.


13. In the **Toolpaths Manager** click on the folder **Parameters** for the **third** operation as shown below:





14. All the parameters and values you set in the first contour operation will still be set. **No changes required for:** Tool, Cut Parameters, Lead/In/Out, Linking Parameters, Planes and Coolant.




15. Select **Multi Passes** from the list on the left and ensure **Multi Passes** are activated by clicking on the small Multi Passes box. Make changes to this page as shown below:




16. Select the OK button  to exit Contour parameters.
17. Select the **Regenerate all dirty operations** button  to remove the red X from the contour operation you have just edited.
18. Save your Mastercam file.
19. Backplot this toolpath.

## TASK 8: MACHINE REMAINING FACES OF SQUARE USING TRANSFORMTOOLPATH




☞ In this task you will use **Toolpaths>Transform** to machine the remaining faces of the square.

1. In the Toolpaths manager **select only the third contour** operation, as indicated by the blue checkmarks shown below.



2. From the menu bar select **Toolpaths>Transform...**
3. On the **Types and Methods** page set the following. Ensure there is a check for the contour operation in the **Source operations** list. Set options as shown below:







- Now click on the **Rotate** tab and set the following. If required click on the Select view icon and select **RIGHT SIDE**.

The screenshot shows the 'Rotate' dialog box with the following settings:

- Instances:** # 3
- Rotation view:**  Rotation view, with a dropdown menu set to 'RIGHT SIDE'.
- Rotation angles:** X: 0.0, Y: 0.0, Z: 0.0
- Start angle:** -90.0
- Rotation angle:** -90.0


**Start angle**  
  
 Sets the beginning angle for the rotate toolpath.

**Rotation angle**  
  
 Sets the angle of rotation for the transform toolpath.

- Select the OK button  to exit the **Transform Operations Parameters** dialog box.
- Save** your Mastercam file.
- Activate a shaded view by selecting the icon at the top of the screen. .
- Backplot all the toolpaths. To pick all the operations to Backplot pick the **Select All** icon .

## TASK 9: MACHINE POCKET ON BACK FACE

- In this task you will use a 0.25" diameter flat end mill to rough and finish the pocket on the BACK face using Toolpath>Pocket.
- In this task you will not use the standard **BACK Tplane**, but will create a new Tplane using Rotate planes from the Planes menu on the Status bar.



1. Select **Alt-T** on your keyboard to **turn off** the display of toolpaths.

2. Set the graphics view to **Isometric View**.




3. Select the **Screen Fit** icon found at the top of the screen to fit the part to the screen.




4. Activate a shaded view by selecting the icon at the top of the screen.




5. Select **Planes** from the Status bar.



6. Select **Rotate planes**.




7. Set the About X value to -90.



8. Click on the OK button when done.




9. In the New View dialog box change the name to **NEW VIEW BACK**. Make changes as shown below:




10. Click on the OK button when done .

11. At the bottom of the graphics screen you will now see **T/Cplane: NEW VIEW BACK**



12. Dynamically rotate the display similar to the display shown below. The text **BACK** is facing up.




**Note**  
At the bottom of the graphics screen the status of the Tool and Construction plane is set to **NEW VIEW BACK**.



13. Activate a wireframe view by selecting the icon at the top of the screen.


14. From the menu bar select **Toolpaths>Pocket...**


15. On the screen you will now see the **Chaining dialog box**. Activate **C-Plane** and ensure **Chain** is selected.





## Mastercam Training Guide

16. On the graphics screen is now a prompt to **Select pocket chain 1** Zoom in as required and select the line at the **top** of the BACK pocket as shown below:




17. After selecting the line your graphics screen should look like the screenshot below, with the **green arrow pointing left** in a clockwise direction. If the arrow is not pointing to the left select the arrow  from the Chaining dialog box to reverse the direction.




18. After the chain has been successfully chained select the OK button  at the bottom of the Chaining dialog box.


19. Ensure the **Toolpath Type** is set to **Pocket**.




20. On the left of the dialog box select **Tool**. Click on the **Select library tool** button and choose a **1/4" Flat End Mill**. . Make changes to this page as shown below:




21. Select **Cut Parameters** from the list on the left and make changes to this page.




22. Select **Roughing** from the list on the left and make changes to this page.



23. Select the plus sign to the left of **Roughing** to expand the list (if required) and click on **Entry Motion** and make changes to this page.




24. Select **Finishing** from the list on the left and make changes to this page:




25. Select the plus sign to the left of **Finishing** expanding the list and click on **Lead In/Out**.


26. Ensure the **Lead In/Out** is activated by clicking on the small Lead In/Out box and make certain the green check mark is showing. Make the following changes as shown below:



27. Select **Depth Cuts** from the list on the left and make changes to this page:




28. Select **Break Through** from the list on the left and make changes to this page:






29. Select **Linking Parameters** from the list on the left and make changes to this page as shown below.




30. Scroll down the list on the left and select **Planes(WCS)**. Set the Work offset to **Zero**.



**Work Offset #**  
Assigns a work offset code to the view. When you use the view for a Tplane and create a toolpath (or wirepath),

Mastercam will automatically output the work offset when you post the operation. Number the offsets sequentially from zero, or enter -1 to not assign any offset to the view.

31. When confronted with the **Update View** dialog box activate **Update just this operation without changing the view.**



32. Click on the OK button when done .
33. Select **Coolant** from the list on the left. Open up the drop down menu for **Flood** and set it to **On**.
34. Select the OK button  to exit Pocket operation.
35. **Save** your Mastercam file.
36. Backplot this toolpath only.


**TASK 10:**  
**MACHINE OPEN POCKET ON BOTTOM FACE**

☞ In this task you will use the 0.25" diameter flat end mill to rough and finish the open pocket on the bottom face using Toolpath> Pocket.


1. If required select **Alt-T** on your keyboard to **turn off** the display of toolpaths.
2. Activate a shaded view by selecting the icon at the top of the screen.




3. Open the **Plane** drop down menu on the Top toolbar and select **Named Views...**




4. You will be confronted with the **View Selection** dialog box, select **BOTTOM** and de-activate **Set new origin** as shown below:



5. Select the OK button  to exit the **View Selection** dialog box.

- Dynamically rotate the display similar to the display shown below. The text **BOTTOM** is facing up.



### Note


At the bottom of the graphics screen the status of the Tool and Construction plane is set to **BOTTOM**.

- Activate a wireframe view by selecting the icon at the top of the screen.





- From the menu bar select **Toolpaths>Pocket...**


- On the screen you will now see the **Chaining dialog box**. Activate **C-Plane** and select **Partial chain**.




10. On the graphics screen is now a prompt to **Select the first entity**. Zoom in as required and select the line at the **bottom** of the pocket as shown below:



11. After selecting the line your graphics screen should look like the screenshot below, with the **green arrow pointing right** in a clockwise direction. If the arrow is not pointing to the right select the arrow  from the Chaining dialog box to reverse the direction.




12. After selecting the first line in the Partial chain you are then prompted to **Select the last entity**. Select the line at the **bottom** of the slot as shown below:




13. After the contour has been successfully chained select the OK button  at the bottom of the Chaining dialog box.


14. Ensure the **Toolpath Type** is set to **Pocket**.




15. On the left of the dialog box select **Tool**. Select the **1/4" Flat End Mill**. Make changes to this page as shown below:




16. Select **Cut Parameters** from the list on the left and make changes to this page. The Pocket type should be set to **Open**. Activate **Use open pocket cutting method**.




17. Select **Roughing** from the list on the left and make changes to this page.



18. Select the plus sign to the left of **Roughing** to expand the list (if required) and click on **Entry Motion**.




19. Select **OFF** in the Entry Motion page.






20. Select **Finishing** from the list on the left and make changes to this page:




21. Select the plus sign to the left of **Finishing** expanding the list and click on **Lead In/Out**.


22. Ensure the **Lead In/Out** is activated by clicking on the small Lead In/Out box and make certain the green check mark is showing. Make the following changes as shown below:




23. Depth Cuts and Break Through should not be activated.



24. Select **Linking Parameters** from the list on the left and make changes to this page as shown below.



25. Scroll down the list on the left and select **Planes(WCS)**. Set the Work offset to **Zero**.



**Work Offset #**  
 Assigns a work offset code to the view. When you use the view for a Tplane and create a toolpath (or wirepath),

Mastercam will automatically output the work offset when you post the operation. Number the offsets sequentially from zero, or enter -1 to not assign any offset to the view.

26. Select **Coolant** from the list on the left. Open up the drop down menu for **Flood** and ensure it is set to **On**.


27. Select the OK button  to exit Pocket operation.

28. **Save** your Mastercam file.

29. Backplot this toolpath

### TASK 11: MACHINE POCKET ON TOP FACE


- In this task you will use a 0.25" diameter flat end mill to rough and finish the pocket on the **TOP** face
- For this example you will copy the fifth operation used to machine the pocket on the **BACK** face and then modify this copied operation to machine the pocket on the **TOP** face.



1. Set the graphics view to **Isometric View**.



2. Activate a shaded view by selecting the icon at the top of the screen.
3. Now dynamically rotate the display similar to the display shown below. The text **TOP** is facing up.




#### Note

At the bottom of the graphics screen the status of the **Tool and Construction** plane is set to **TOP**.


- Before moving on, let's organize the operations in the Toolpaths Manager. Click on the minus sign for each operation to collapse the tree structure of these operations.






- In the Toolpaths manager **select only the fifth Pocket** operation, as indicated by the blue checkmarks shown below. This fifth operation is used to machine the pocket on the **BACK** face.



- To copy this operation **Hold down the Right mouse button over fifth**. **Keep holding the right mouse button** down and drag below the red arrow and release.
- Select **Copy after** from this menu.




- Your screen will look similar to the screenshot below on the left. Move the Insert arrow to the bottom of the list of operations by clicking the  icon on the Toolpaths Manager toolbar:




## Mastercam Training Guide


9. In the **Toolpaths Manager** click the plus sign to the left of **operation 7 Pocket** to expand the list. Now click on the folder **Parameters** for the **seventh** operation as shown below:




10. All the parameters and values you set earlier in this copied pocket operation will **still be set**. **The Only changes required are for Linking Parameters and Planes (WCS)**. Select **Linking Parameters** and make changes to this page as shown below. The **Depth** is set in Incremental at a depth of -0.25.



11. Scroll down the list on the left and select **Planes(WCS)**. The Tool plane and Construction plane is set to **NEW VIEW BACK** at present. You need to change the Tool plane to **TOP**. Click on the **Select tool plane view** icon.




12. In the View Selection dialog box select **TOP** and un-check **Set new origin**.




13. Click on the OK button when done.

14. When returned to the Planes page note now that the **Tool plane is set to TOP**, but the **Comp / construction plane is set to NEW VIEW BACK**. Click on the **right Copy button** to transfer the Tool plane settings over to the Comp / construction plane settings.



15. Now set the Work offset to **Zero**.




16. When confronted with the **Update View dialog box** activate **Update just this operation without changing the view**.


17. Click on the OK button in the **Update View dialog box** when done .

18. Select the OK button  to exit Pocket parameters.

19. Now click on the **Geometry icon** for the **seventh** operation as shown below:




20. In the Chain Manager right mouse click on **Chain 1** and select **Rechain all**.






21. On the screen you will now see the **Chaining dialog box**. Activate **C-Plane** and ensure **Chain** is selected.



**Cplane**


Chains only entities that are parallel to the current construction plane and at the same Z depth as the first entity you chain. In Window, Area, or Polygon chaining, chains only entities that are on the current construction plane and at the current Z depth.


22. On the graphics screen is now a prompt to **Add chain 1**. Zoom in as required and select the line in this pocket as shown below:






**Note**

At the bottom of the graphics screen the status of the **Tool and Construction plane** is now set to **TOP**.


23. After selecting the line your graphics screen should look like the screenshot below, with the **green arrow pointing left**. If the arrow is not pointing to the left select the arrow  from the Chaining dialog box to reverse the direction.



24. After the contour has been successfully chained select the OK button  at the bottom of the Chaining dialog box.
25. Select the OK button  at the bottom of the Chain Manager box.
26. Select the **Regenerate all dirty operations** button  to remove the red X from the contour operation you have just edited.
27. Click on the minus sign to the left of this last operation to collapse it.
28. Save your Mastercam file.
29. Backplot this toolpath.

**TASK 12:  
DRILL HOLES ON FRONT FACE**


☞ In this task you will drill the two holes on the front face with a 0.25" centre cutting Flat End Mill.



1. Activate a shaded view by selecting the icon at the top of the screen.




2. Dynamically rotate the display similar to the display shown below. The text **TOP** is facing up.



**Note**  
At the bottom of the graphics screen the status of the Tool and Construction plane is set to **TOP**.

3. Open the **Plane** drop down menu on the top toolbar and select **FRONT (WCS)**.




4. At the bottom of the graphics screen you will now see **T/Cplane: FRONT**



## Mastercam Training Guide


- From the menu bar select **Toolpaths>Drill...**
- Now you are prompted to Select points and the Drill Point Selection dialog box appears. All you need to do now is snap to the centre of the two circles. Move the mouse and position the cursor over the **center of the left circle shown below**, you will notice a circle appears as you move closer to the center of the circle, this is the visual cue for Arc center. **Ensure the visual cue for Arc center point appears** before you select the point. Use the left button of your mouse to pick this center point. Now select the centre of the **second** hole using the same method.




- Select the OK button  in the **Drill Point Selection** dialog window to complete the selection of points.
- Ensure the **Toolpath Type** is set to **Drill**.



- Select the **1/4" flat end mill**. Change the page parameters as shown below:




10. Select the **Linking Parameters** page and make the changes as shown below.



11. Tip Comp **should not** be activated.

12. From the list on the left select **Planes(WCS)**. Ensure the values are as below. Work offset to **Zero**.



13. Select the **Coolant** page, and set **Flood** to **On**:

14. Select the **OK** button  to complete this drilling function.


15. Click on the minus sign to the left of this last operation to collapse it.



16. Save your Mastercam file.


17. Backplot this toolpath.

## TASK 13: DRILL HOLE ON HEXAGON AT FRONT

- ☛ In this task you will drill the hole on the hexagon at the front with a 0.25" centre cutting Flat End Mill.




1. Select an Isometric view  and then Screen Fit .
2. Dynamically rotate the display similar to the display shown below. The text **TOP** is facing up.




**Note**  
At the bottom of the graphics screen the status of the Tool and Construction plane is set to **TOP**.

3. Select **WCS>View Manager** from the Status bar.




4. From the **View Manager Dialog** box select the **Geometry** button as shown below.




**Geometry**  
Click the Geometry button to create a new view based on geometry in your part.  
Mastercam will prompt you for the necessary geometry and other information needed to create the view.

- At the graphics screen you will be prompted to: **Set construction plane by geometry Cplane by geometry**. Select the **arc of the hole** shown below. Make sure the **XYZ tripod** is the same as the example below right with the **Z axis** arrow pointing up from the hole, **X axis** pointing to the right as shown below right. Use the **arrow buttons** in the Select view screen to cycle through to the correct coordinate system.




- Select the green check mark for **OK**.
- In the **New View** dialog box enter **NEW VIEW HEX HOLE** in the name section. Un-check **Set new origin**.




- Click on the OK icon to complete this feature.
- Now you are back in the View Manager dialog box pick in the **C (Cplane)** column and **T (Tplane)** column of the **NEW VIEW HEX HOLE** row as shown below.

Name	C	T	D	Woff #
TOP			X	
FRONT			X	0
BACK			X	
BOTTOM			X	0
RIGHT SIDE			X	
LEFT SIDE			X	
ISO			X	
NEW VIEW BACK			X	
NEW VIEW HEX HOLE	C	T	X	

10. In the lower right of the view manager dialog window change the origin coordinates to **X0 Y0 Z0**.



11. Your View Manager dialog box should look like the image below:



12. Click on the **OK** icon  to complete this feature.


13. At the bottom of the graphics screen you will now see **T/Cplane: NEW VIEW HEX HOLE (Not Saved)**

Gview:Not Saved    WCS:Not Saved    T/Cplane:NEW VIEW HEX HOLE (Not Saved)




14. From the menu bar select **Toolpaths>Drill...**

15. Now you are prompted to Select points and the Drill Point Selection dialog box appears. All you need to do now is snap to the centre of the circle. Move the mouse and position the cursor over the **center of the circle shown below**, you will notice a circle appears as you move closer to the center of the circle, this is the visual cue for Arc center. **Ensure the visual cue for Arc center point appears** before you select the point. Use the left button of your mouse to pick this center point.





16. Select the OK button  in the **Drill Point Selection** dialog window to complete the selection of points.

17. Ensure the **Toolpath Type** is set to **Drill**.






21. From the list on the left select **Planes(WCS)**. Ensure the values are as below. Work offset to **Zero**. Click on the View Selection button to select a new view .



22. When confronted with the **Update View** dialog box activate **Update just this operation without changing the view.**



23. Click on the OK button when done .

24. Select the **Coolant** page, and set **Flood** to **On**:

25. Select the **OK** button  to complete this drilling function.


26. Click on the minus sign to the left of this last operation to collapse it.

27. Save your Mastercam file.


28. Backplot this toolpath.

## TASK 14: DRILL HOLE ON HEXAGON AT BACK USING TRANSFORM TOOLPATH


- In this task you will a drill hole on the hexagon with a 0.25" centre cutting Flat End Mill.
- You will use **Toolpath>Transform** to drill the hole on the back face of the hexagon.



1. In the Toolpaths manager **select only the ninth operation**, as indicated by the blue checkmarks shown below.





2. From the menu bar select **Toolpaths>Transform...**
3. On the **Types and Methods** page set the following. Ensure there is only a check mark for the ninth drill operation in the **Source operations** list. Set options as shown below:




- Now click on the **Rotate** tab and set the following. If required click on the Select view icon and select **RIGHT SIDE**.

The screenshot shows the 'Transform Operations Parameters' dialog box for a rotate operation. The 'Instances' section is set to 1. The 'Rotation view' is set to 'RIGHT SIDE'. The rotation angles for X, Y, and Z are 0.0. The start and end angles for the toolpath are both set to -120.0. A callout box on the right explains the 'Start angle' and 'Rotation angle' icons.

**Start angle**  
  
 Sets the beginning angle for the rotate toolpath.

**Rotation angle**  
  
 Sets the angle of rotation for the transform toolpath.

- Select the OK button  to exit the **Transform Operations Parameters** dialog box.
- Click on the minus sign to the left of this last operation to collapse it.
- Save your Mastercam file.
- Backplot this toolpath.


### TASK 15:


#### VERIFY THE TOOLPATHS USING A SUPPLIED STL FILE

- ☞ Mastercam's Verify utility allows you to use solid models to simulate the machining of a part.
- ☞ If you are using a Training Guide to go through this Lesson the required STL file is on the multimedia DVD that came with this text in a folder called Mastercam Files. If you are using the Online Course content this file is available in Step 2 of this Lesson on the online content screen.

1. Locate the supplied STL file **FOUR-AXIS-LESSON-3.STL** and copy the file to the same folder that your Mastercam files resides in.
2. For a better view of the part use the toolbar at the top of the screen to change the graphics view to Isometric.




3. Select the **Screen Fit** icon found at the top of the screen to fit the part to the screen .
4. Now dynamically rotate the display similar to the display shown below. The text **TOP** is facing up.




5. In the Toolpaths Manager pick all the operations to verify by picking the Select All icon .
6. In the Toolpaths Manager pick the **Backplot/Verify Options** icon.




- In the **Backplot/Verify Options** window activate the radio button for **File** and then select the **Browse** icon.




- Select the **FOUR-AXIS-LESSON-3.STL** file and then click on **Open**. **Please Note:** The STL file is supplied on the multimedia DVD that came with this text in a folder called Mastercam Files.
- Select the **OK** button  to exit **Backplot/Verify Options**.
- Select the **Verify selected** operations button shown below:



- Maximize** the Backplot/Verify window if required.
- Activate the options shown below in the **Visibility** section of the Home tab. Initial Stock and Toolpath not activated.



13. The stock appears as below:





14. Activate the **Color Loop** to change the color of the tools for the verified part.

15. In the lower right corner of the screen now set the run **Speed** to slow by moving the slider bar pointer over to the left as shown below.




16. Now select the Play Simulation button to review the toolpaths.




17. Select the **Close** button  in the top right hand corner to exit Verify.




**TASK 16:  
POST AND CREATE THE CNC CODE FILE**


1. Ensure all the operations are selected by picking the **Select All** icon  from the Toolpaths Manager.
2. Select the **Post selected operations** button from the Toolpaths Manager.



3. In the Post processing window, make the necessary changes as shown below:



4. Select the OK button  to continue.
5. Click on OK in the Work offset dialog box.



6. Enter the same name as your Mastercam part file name in the NC File name field **FOUR-AXIS-LESSON-3**.
7. Select the **Save** button.

8. Scroll down and review the NC file. Note the various **A-Axis** moves to machine the pockets and holes.

```
FOUR-AXIS-LESSON-3.NC x
1  %
2  O3
3  (FOUR-AXIS-LESSON-3)
4  (DATE=DD-MM-YY - 09-04-13 TIME=HH:MM - 14:31)
5  (MCX FILE - G:\CAMINSTRUCTOR-IN-WORK\MASTERCAMX5-MULTI-AXIS-LESSONS\FOUR-AXIS-LESSON-3\COMPLETED\FOUR-AXIS-LESSON-3.MCX-7)
6  (NC FILE - C:\USERS\NEW\DOCUMENTS\MY_MCAMX7\MILL\NC\FOUR-AXIS-LESSON-3.NC)
7  (MATERIAL - ALUMINUM INCH - 6061)
8  (T1| 3/4 FLAT ENDMILL|H1|D1|TOOL DIA. - .75)
9  (T2| 1/4 FLAT ENDMILL|H2|D2|TOOL DIA. - .25)
10 N1 G20
11 N2 G0 G17 G40 G49 G80 G90
12 N3 T1 M6
13 N4 G0 G90 G54 X-1.405 Y-1.1469 A0. S3000 M3
14 N5 G43 H1 Z2.
15 N6 M8
16 N7 Z.9375
17 N8 G1 Z.6875 F7.
18 N9 X-.655
```

9. Select the  in the top right corner to exit the CNC editor.  
10. This completes **Four-Axis-Lesson-3**.

### FOUR-AXIS-LESSON-3 EXERCISES

- ⇒ If you are using a Training Guide the required exercise files are on the multimedia DVD that came with this text in a folder called Mastercam Files. If you are using the Online Course content the exercise files are available in this Lesson on the online content screen.

#### FOUR-AXIS-LESSON-3 EXERCISE #1



#### FOUR-AXIS-LESSON-3 EXERCISE #2



FOUR-AXIS-LESSON-3 EXERCISE #1

